

# SSS Magnetic measurement review

11 Feb 05

- Systematic calibration errors found
  - Optical system was not well understood
- All data, Fidu + Magn to be retreated (no need to re-measure)
- Mas dbase to be re-loaded with new packages
  - Shall be done 25.02
- H & V geometry +magn axis closer to '0'
- I proposed to re-measure one SSS and to compare retreated with fresh data → endorsed by Louis